



Detailed Site Investigation

A financial institution was seeking to understand the financial situation of a former service station facility located near the beach.

Services Provided

- A review of existing reports and a data gap analysis
- Development of a Sampling Analysis and Quality Plan
- Soil investigation
- Assessment of soil lithology
- Exposure pathway investigations
- Discussion of analytical results
- Opinion on the potential financial liability associated with the site

Project Title:
Detailed Site Investigation

Client:
Financial Institution

Location:
Turners Beach, Tasmania

Project Value:
\$25K

Project Outcome

Recommendations outlined in the EP Risk Management report along with consultation with relevant stakeholders allowed for the client to understand their potential risk associated with environmental conditions.

For further information contact:

Ph: 038540 7300 **Web:** www.eprisk.com.au